This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

... rage i oi is





FIGURE 1 - PRIOR ART







FIGURE 3 - PRIOR ART

Rim 120

- Wheel Assembly 118

FIGURE 4 - PRIOR ART






FIGURE 5 - PRIOR ART




FIGURE 6 - PRIOR ART




FIGURE 7 - PRIOR ART








FIGURE 8 - PRIOR ART









Inventor: David Voeller, et al. Page 5 of 13



F I G. 12









FIGURE 15








FIGURE 17










FIGURE 23 - PRIOR ART

Inventor: David Voeller, et al. Page 9 of 13

Inventor: David Voeller, et al. Page 10 of 13




Inventor: David Voeller, et al. Page 11 of 13



400

Inventor: David Voeller, et al. Page 12 of 13







FIGURE 24 – PRIOR ART






FIGURE 26